



5030HS




Length (mm)	50	100	150	200		
Deg C/W	5.00	3.00	2.30	2.10		

5308HS




Length (mm)	50	100	150	200		
Deg C/W	2.80	1.60	1.20	1.05		

5050HS




Length (mm)	50	100	150	200		
Deg C/W	3.30	2.30	1.80	1.65		

5400HS




Length (mm)	50	100	150	200	300	
Deg C/W	1.50	1.10	0.85	0.75	0.70	

5100HS




Length (mm)	50	100	150	200		
Deg C/W	2.50	1.50	1.20	1.10		

5410HS




Length (mm)	50	100	150	200	300	
Deg C/W	1.45	0.90	0.75	0.65	0.60	

5150HS




Length (mm)	50	100	150	200		
Deg C/W	2.10	1.40	1.10	0.95		

5420HS




Length (mm)	50	100	150	200	300	
Deg C/W	1.00	0.75	0.50	0.40	0.35	

5160HS



Length (mm)	50	100	150	200		
Deg C/W	1.35	0.80	0.65	0.55		

5430HS



Length (mm)	50	100	150	200	300	
Deg C/W	1.10	0.78	0.52	0.42	0.40	