



1040HS




Length (mm)	50	100	150	200	300
Deg C/W	2.65	1.95	1.60	1.41	1.32

1064HS




Length (mm)	50	100	150	200
Deg C/W	1.70	1.30	1.20	1.15

1059HS




Length (mm)	50	100	150	200	300
Deg C/W	3.30	2.40	2.00	1.75	1.60

1066HS




Length (mm)	50	100	150	200
Deg C/W	1.50	1.00	0.80	0.72

1061HS




Length (mm)	50	100	150	200
Deg C/W	2.90	1.55	1.07	0.92

1069HS



Length (mm)	50	100	150	200
Deg C/W	1.90	1.40	1.20	1.05

1062HS




Length (mm)	50	100	150	200
Deg C/W	3.00	1.90	1.65	1.45

1071HS




Length (mm)	50	100	150	200	300
Deg C/W	1.40	1.00	0.75	0.65	0.59

1063HS



Length (mm)	50	100	150	200
Deg C/W	1.70	1.30	1.20	1.15

1072HS



Length (mm)	50	100	150	200	300
Deg C/W	1.40	1.00	0.75	0.65	0.59