



1075HS




Length (mm)	50	100	150	200	300	
Deg C/W	1.40	0.90	0.55	0.42	0.38	

1088HS




Length (mm)	50	100	150	200		
Deg C/W	6.00	4.60	4.00	3.80		

1077HS




Length (mm)	50	100	150	200	300	
Deg C/W	1.20	0.80	0.50	0.40	0.34	

1090HS



Length (mm)	50	100	150	200	300	
Deg C/W	1.80	1.10	0.86	0.73	0.65	

1082HS




Length (mm)	50	100	150	200	300	
Deg C/W	0.70	0.46	0.36	0.30	0.27	

1124HS




Length (mm)	50	100	150	200		
Deg C/W	6.00	4.60	4.20	3.80		

1085HS




Length (mm)	50	100	150	200		
Deg C/W	7.50	6.00	5.10	4.90		

1126HS




Length (mm)	50	100	150			
Deg C/W	6.50	4.60	4.00			

1086HS



Length (mm)	50	100	150	200	300	
Deg C/W	0.55	0.42	0.38	0.35	0.32	

1128HS



Length (mm)	50	100	150	200		
Deg C/W	3.20	2.40	2.15	2.00		