



1130HS




Length (mm)	50	100	150			
Deg C/W	10.00	7.10	6.40			

1142HS




Length (mm)	50	100	150	200		
Deg C/W	2.00	1.40	1.00	0.75		

1132HS




Length (mm)	50	100	150			
Deg C/W	4.50	3.40	3.00			

1146HS




Length (mm)	50	100	150	200		
Deg C/W	2.00	1.40	1.00	0.75		

1135HS




Length (mm)	50	100	150	200	300	
Deg C/W	3.30	2.50	2.00	1.80	1.70	

1148HS



Length (mm)	50	100	150	200		
Deg C/W	2.20	1.40	1.00	0.95		

1138HS




Length (mm)	50	100	150			
Deg C/W	3.00	2.10	1.80			

1150HS




Length (mm)	50	100	150	200		
Deg C/W	1.60	1.00	0.75	0.72		

1140HS



Length (mm)	50	100	150			
Deg C/W	4.50	3.20	2.90			

1154HS



Length (mm)	50	100	150	200	300	
Deg C/W	3.20	1.75	1.20	1.00	0.90	