



3020HS




Length (mm)	50	100	150	200		
Deg C/W	7.50	6.00	5.00	4.80		

3120HS




Length (mm)	50	100	150	200		
Deg C/W	2.00	1.40	1.20	1.15		

3050HS




Length (mm)	50	100	150	200		
Deg C/W	3.50	2.40	2.00	1.85		

3140HS




Length (mm)	50	100	150	200		
Deg C/W	2.50	1.70	1.50	1.33		

3070HS




Length (mm)	50	100	150	200		
Deg C/W	4.20	3.00	2.20	1.90		

3160HS




Length (mm)	50	100	150	200		
Deg C/W	1.50	1.00	0.90	0.80		

3080HS




Length (mm)	50	100	150	200		
Deg C/W	3.60	2.80	2.30	1.90		

3200HS



Length (mm)	50	100	150	200		
Deg C/W	1.20	0.67	0.50	0.42		

3090HS



Length (mm)	50	100	150	200		
Deg C/W	2.70	2.00	1.75	1.65		

