



7000HS




Length (mm)	50	100	150	200		
Deg C/W	1.80	1.25	1.05	0.95		

7176HS




Length (mm)	50	100	150	200		
Deg C/W	4.00	3.20	2.90	2.75		

7030HS




Length (mm)	50	100	150	200		
Deg C/W	2.50	1.50	1.20	1.05		

7180HS




Length (mm)	50	100	150	200		
Deg C/W	1.40	0.80	0.60	0.50		

7100HS




Length (mm)	50	100	150	200		
Deg C/W	1.50	1.12	0.90	0.85		

7120HS




Length (mm)	50	100	150	200		
Deg C/W	1.30	0.88	0.70	0.60		

7200HS



Length (mm)	50	100	150	200	300	
Deg C/W	0.64	0.46	0.35	0.28	0.24	

7170HS



Length (mm)	50	100	150	200	300	
Deg C/W	2.50	1.45	1.20	1.05	1.00	

